

14th August 2025

Product Change Notification: Minor Change to motor

18/11/22

This letter serves as formal notification Donaldson BOFA have made the following change to the listed items:

Addition of tacho connection as standard to brushless blowers

As part of an ongoing process of product rationalisation, BOFA is now providing all of the below brushless blowers with tacho connection as standard. This simplifies the ordering process for customers, with having one option of this blower.



Original power harness & new
Tacho connection

Original power harness

What does this change mean to you?

Where the tacho connection is required, setup your pump as usual.
For units without tacho connection the extra wires can be neatly positioned out of the way and not used.
If you have any questions, please contact your sales manager.
Orderable spares PN: 1UA1050017

Which units would use the tacho?

Only the AD 1000 iQ and AD 2000 iQ would need the tacho cable to be connected, all the other extractors that are bought by MI won't need the Tacho cable connected and it can be disconnected.

Judi Barlow

Manager Product – Core
Donaldson BOFA