




THE WORLD LEADER IN  
FUME EXTRACTION TECHNOLOGY



Begin by holding the 'Stay-Put' arm either side of the 'weak spot'



Gripping the tube, Push the corrugated joints together as shown.



Now again Firmly gripping the arm with both hands, begin to twist your right hand towards yourself.



You will feel the arm tightening and becoming more rigid.

Be careful not to over tighten as this can cause the arms bore to decrease and in turn will restrict the flow of air.

**Note: If the arm is fitted with the LED Light option, please isolate from mains power before conducting this procedure.**

## BOFA INTERNATIONAL LTD

Tel: +44 (0) 1202 699 444 Fax: +44 (0) 1202 699 446 Email: [info@bofa.co.uk](mailto:info@bofa.co.uk) Web: [www.bofa.co.uk](http://www.bofa.co.uk)

Address: 21-22 Balena Close, Creekmoor Industrial Estate, Poole, Dorset, UK. BH17 7DX

Vat No: GB414037392 Reg No: 2122653